

great energy. balanced me.

Underwood Drinking Water System

2023 Annual Water Summary Report

1. INTRODUCTION AND BACKGROUND

The municipality owns and operates drinking water systems to provide residents with safe, potable water. These municipal drinking water systems are regulated under various legislation and legal documents including the Safe Drinking Water Act and Ontario Regulation 170/03 Drinking Water Systems. O. Reg. 170 requires that the municipality complete an annual water report (Section 11) and an annual summary report (Schedule 22). The information required for each of these reports has been combined into this one report. This annual water summary report will be made available for inspection as per O. Reg. 170 subsection 12 (4).

The reports are available free of charge on the municipal website at <u>www.kincardine.ca</u> or by contacting the Environmental Services Department at <u>waterservice@kincardine.ca</u>. Requests will also be received in person or by telephone at the Municipal Administration Centre (1475 Concession 5, 519-396-3468) or the Environmental Services Office (155 Durham Street, Kincardine, 519-396-4660).

1.1. System Description

Drinking-Water System Number:	220007052
Drinking-Water System Name:	Underwood Drinking Water System
Drinking-Water System Owner:	Municipality of Kincardine
Drinking-Water System Category:	Small Municipal Residential
Period being reported:	Year 2023

The Underwood Drinking Water System (DWS) is a non-GUDI system (which means that it is a secure well and not under the influence of surface water) consisting of a single well located in the hamlet of Underwood. The well is a drilled type with a 203 mm (8 in.) casing and is 122 m (400 ft) deep. It was drilled in August 1972 and is equipped with a submersible pump. Raw and treated water are each metered by mag meters. Sodium hypochlorite (NSF certified) is used for disinfection. There is on-line monitoring of chlorine. There are hydropneumatic tanks located in the control building that provide continuous pressure in the distribution system and allow for intermittent operation of the well pump. A chlorine contact chamber consisting of an 8.3 m length of 600 mm diameter pipe provides the required contact time. This system has a standby generator.

1.2. Major Expenses

The system incurred expenses necessary to install, repair or replace required equipment as follows:

Monitoring Equipment \$28,028.01 Treatment Upgrades \$11,984.33

2. WATER QUALITY MONITORING

Each municipal drinking water system is required to do testing to ensure that the water supplied to consumers is safe for consumption. Some of these tests such as chlorine residuals are done on site while others, like microbiological testing, must be performed by a licenced laboratory.

2.1. Microbiological Testing

O. Reg. 170 Schedule 11, requires the Underwood DWS to take a minimum of one sample per month of raw water from the well, and one sample every two weeks of distribution water and have them tested for Escherichia coli (E. coli) and total coliforms (TC). The distribution samples must also be tested for heterotrophic plate count (HPC). Our internal sampling schedule exceeds the minimum requirements by having operations staff collect one treated and one distribution sample every week and have them tested for E. coli, total coliform and HPC. In addition, the raw water sampling was increased to weekly to monitor for the presence of microorganisms in the raw water. The water was disinfected adequately such that there were no E. coli or total coliform present in the treated or distribution water.

Any E. coli or total coliform results above zero in treated or distribution water must be reported to the Ministry of Environment, Conservation and Parks (MECP) and Medical Officer of Health (MOH).

Heterotrophic plate count is a colony count of general bacteria population. There is no adverse limit for HPC samples. Results over 500 colonies per 1 mL may indicate a change in water quality but it is not considered an indicator of unsafe water.

Water Source	Number of TC/EC Samples	Range of Total Coliform Results (#-#)	Range of E. coli Results (#-#)	Number of HPC Samples	Range of HPC Results (#-#)
Raw	54	0-2	0-0	4	0-3
Treated	53	0-0	0-0	52	$0 - < 10^{*}$
Distribution	52	0-0	0-0	52	0-27*

The results from the 2023 sampling program are shown in the table below.

*Note: One distribution sample and one treated sample showed No Data-Overgrown with HPC results in July, resample results showed no issues.

2.2. Chemical Testing

The Safe Drinking Water Act Reg 170 Schedule 13 requires periodic testing of the water for chemical parameters. The Underwood DWS is required to test for nitrite/nitrate and trihalomethanes on a quarterly basis. Haloacetic acid is required to be tested on a quarterly basis every third year due to its low levels in the system. The tables below outline other inorganic and organic parameters that are required to be tested every five years and include the date and result of the most recent test. Any result displayed as less than (<) are below the method detection limit of the lab.

Sodium and fluoride levels exceed the Ontario Drinking Water Quality Standards, but they are naturally occurring in the groundwater and do not need to be tested more frequently than every five years.

If the concentration of a parameter is above half of the Maximum Acceptable Concentration (MAC) under the Ontario Drinking Water Quality Standards, an increased testing frequency of once every three months is required by O. Regulation 170. Arsenic is naturally occurring in the raw water and is tested for quarterly. The maximum acceptable concentration of arsenic in drinking water is $10 \mu g/L$.

Inorganic	Sample Date	Result	Unit of	Exceedance
Parameter	_	Value	Measure	
Antimony	July 10/23	0.6	μg/L	No
Arsenic	January 19/23	5.7	μg/L	No
	April 11/23	6.4		
	July 10/23	5.3		
	October 10/23	5.3		
Barium	July 10/23	20.1	μg/L	No
Boron	July 10/23	239	μg/L	No
Cadmium	July 10/23	0.008	μg/L	No
Chromium	July 10/23	0.17	μg/L	No
Mercury	July 10/23	< 0.01	μg/L	No
Selenium	July 10/23	0.04	μg/L	No
Sodium	October 12/22	69.6	mg/L	Yes
	October 18/22	57.3		
Uranium	July 10/23	0.516	μg/L	No
Fluoride	April 11/23	1.75	mg/L	Yes
	April 17/23	1.61		
Nitrite	January 19/23	< 0.003	mg/L	No
	April 11/23	< 0.003		
	July 10/23	< 0.003		
	October 10/23	< 0.003		
Nitrate	January 19/23	0.008	mg/L	No
	April 11/23	0.010		
	July 10/23	0.009		
	October 10/23	0.009		

Organic Parameter	Sample Date	Result	Unit of	Exceedance
_	_	Value	Measure	
Alachlor	July 10/23	< 0.02	μg/L	No
Atrazine + N-dealkylated metabolites	July 10/23	< 0.01	μg/L	No
Azinphos-methyl	July 10/23	< 0.05	μg/L	No
Benzene	July 10/23	< 0.32	μg/L	No
Benzo(a)pyrene	July 10/23	< 0.004	μg/L	No
Bromoxynil	July 10/23	< 0.33	μg/L	No
Carbaryl	July 10/23	< 0.05	μg/L	No
Carbofuran	July 10/23	< 0.01	μg/L	No
Carbon Tetrachloride	July 10/23	< 0.17	μg/L	No
Chlorpyrifos	July 10/23	< 0.02	μg/L	No
Diazinon	July 10/23	< 0.02	μg/L	No
Dicamba	July 10/23	< 0.20	μg/L	No
1,4-Dichlorobenzene	July 10/23	< 0.36	μg/L	No
1,2-Dichlorobenzene	July 10/23	< 0.41	μg/L	No
1,2-Dichloroethane	July 10/23	< 0.35	μg/L	No
1,1-Dichloroethylene	July 10/23	< 0.33	μg/L	No
(vinylidene chloride)				
Dichloromethane	July 10/23	< 0.35	μg/L	No
2-4 Dichlorophenol	July 10/23	< 0.15	μg/L	No
2,4-Dichlorophenoxy acetic acid (2,4-D)	July 10/23	< 0.19	μg/L	No
Diclofop-methyl	July 10/23	< 0.40	μg/L	No
Dimethoate	July 10/23	< 0.06	μg/L	No
Diquat	July 10/23	< 1	μg/L	No
Diuron	July 10/23	< 0.03	μg/L	No
Glyphosate	July 10/23	< 1	μg/L	No
Malathion	July 10/23	< 0.02	μg/L	No
2 methyl-4-chlorophenoxyacetic acid	July 10/23	< 0.00012	μg/L	No
(MCPA)				
Metolachlor	July 10/23	< 0.01	μg/L	No
Metribuzin	July 10/23	< 0.02	μg/L	No
Monochlorobenzene	July 10/23	< 0.3	μg/L	No
Paraquat	July 10/23	< 1	μg/L	No
Pentachlorophenol	July 10/23	< 0.15	μg/L	No
Phorate	July 10/23	< 0.01	μg/L	No
Picloram	July 10/23	< 1	μg/L	No
Polychlorinated Biphenyls (PCB)	July 10/23	< 0.04	μg/L	No
Prometryne	July 10/23	< 0.03	μg/L	No
Simazine	July 10/23	< 0.01	μg/L	No
Terbufos	July 10/23	< 0.01	μg/L	No
Tetrachloroethylene	July 10/23	< 0.35	μg/L	No
2,3,4,6-Tetrachlorophenol	July 10/23	< 0.20	μg/L	No
Triallate	July 10/23	< 0.01	μg/L	No
Trichloroethylene	July 10/23	< 0.44	μg/L	No
2,4,6-Trichlorophenol	July 10/23	< 0.25	μg/L	No
Trifluralin	July 10/23	< 0.02	μg/L	No
Vinyl Chloride	July 10/23	< 0.17	μg/L	No

Trihalomethane (THM) distribution sampling is required quarterly and must also be expressed as a running annual average. The limit as set in the Ontario Drinking Water Quality Standards is 100 ug/L. Trihalomethanes are a by-product of the disinfection process.

Date Sampled	THM Result Value (µg/L)	Running Annual Average (µg/L)	Exceedance
January 9/23	51	64.3	No
April 11/23	59	69.3	No
July 10/23	86	78.3	No
October 10/23	80	69.0	No

Sampling and testing for haloacetic acids (HAA) in the distribution system is a new requirement as of 2017. They are also required quarterly every third year as log as the results are below the limit. The limit as set in the Ontario Drinking Water Quality Standards is 80 ug/L and starting in 2020 must also be expressed as a running annual average. Haloacetic acids are a by-product of the disinfection process.

Date Sampled	HAA Result Value (µg/L)	Running Annual Average (µg/L)	Exceedance
January 9/23	11.2	11.2	No
April 11/23	6.4	8.8	No
July 10/23	< 5.3	7.6	No
October 10/23	< 5.3	7.1	No

The Underwood DWS does not have significant levels of lead and so is currently under a reducedsampling program. Under this sampling program, O. Reg 170 Schedule 15.1 requires sampling for lead every three years and lead-related parameters (pH and alkalinity) every year. PH and Alkalinity sampling was performed in 2023, below are the results.

Date Sampled	Location	Number	Parameter	Results
	Туре	of		
		Samples		
April 3, 2023	Distribution	1	pН	8.4
			Alkalinity (mg/L)	109
August 14, 2023	Distribution	1	pН	7.8
			Alkalinity (mg/L)	108

2.3. Operational Monitoring

Sodium hypochlorite is used for primary and secondary disinfection. The free chlorine residual is monitored continuously on the treated water and must be checked a minimum of twice per week in the distribution system.

As a target, the free chlorine residual should be above 0.20 mg/L. A distribution free chlorine level lower than 0.05 mg/L must be reported to the Ministry of the Environment and the Ministry of Health and corrective action taken.

Our internal sampling schedule exceeds the minimum requirements by having operations staff collect one distribution free chlorine residual every day.

Free Chlorine	Number of Grab	Range of Results
Treated Water	Continuous monitoring	-0.12 - 4.87
Distribution Water	365	0.41 – 1.73

Notes:

- 1. March-New wiring from PLC to SCADA caused a negative reading for the minimum chlorine residual to be recorded.
- 2. June-Low cl2 alarms caused residuals of 0.01mg/L and 0.13mg/L to be recorded on June 10 and 15 during backflushing. The system was locked out and water was not directed to users.
- 3. July-Low cl2 alarm caused residual of 0.03mg/L to be recorded. The system was locked out and water not directed to users.
- 4. December-Low cl2 residual of 0.13mg/L was simulated for monthly lockout valve testing.

O. Reg 170 Schedule 7 requires that turbidity in the raw water is tested at least once every month. Consistent turbidity results greater than 5 NTU could indicate surface water influence on the well.

Raw Water	Number of Grab Samples	Range of Results (#-#)	
Turbidity	52	0.13 - 0.58	

3. WATER QUANTITY

The following tables list the quantities and flow rates of the water supplied to the distribution system during the reporting period covered by this report, including monthly average and maximum daily flows and a comparison to the rated capacity specified in the system Municipal Drinking Water Licence. The rated capacity of the treatment system is 90.8 m³/day. There is no maximum flow rate specified for water supplied to the distribution system.

Month	Total Treated Flow (m3)	Average Daily Flow (m ³ /day)	% Average Day/Rated Capacity (m ³ /day)	Maximum Daily Flow (m ³ /day)	% Maximum Day/Rated Capacity (m ³ /day)
January	269	9	11%	14	18%
February	298	11	14%	48	62%
March	291	9	12%	13	16%
April	284	9	12%	16	21%
May	336	11	14%	23	30%
June	364	12	16%	21	27%
July	348	11	14%	17	21%
August	376	12	16%	16	20%
September	324	11	14%	16	20%
October	357	12	15%	14	18%
November	327	11	14%	16	21%
December	336	11	14%	15	19%
Annual	3,911	11	14%	48	62%

Month	Average Daily Flow Rate (L/s)	Maximum Daily Flow Rate (L/s)
January	0.10	1.72
February	0.12	2.77
March	0.11	2.17
April	0.11	3.09
May	0.13	3.03
June	0.14	3.03
July	0.13	3.03
August	0.14	3.03
September	0.13	3.03
October	0.13	3.03
November	0.13	2.98
December	0.13	2.62
Annual	0.12	3.09

4. ADVERSE WATER QUALITY INCIDENTS AND NON-COMPLIANCE FINDINGS

Any adverse results from microbiological samples, chemical samples or observations of operational conditions that indicate adverse water quality are reported to the Spills Action Centre (SAC) of the Ministry of The Environment, Conservation and Parks and the Medical Officer of Health (MOH). All adverse conditions are responded to immediately and corrective actions taken. There was one reportable incident in 2023 for Fluoride.

Incident Date	Parameter	Result	Corrective Action	Corrective Action Date
April 13, 2023 AWQI# 161745	Fluoride above MAC limit of 1.5 mg/L	1.75 mg/L	Resampled and annual notification given to system users	April 17, 2023

The annual MECP Inspection took place on April 13, 2023, for the period of April 21, 2022 to April 13, 2023. The inspection report did not identify non-compliance issues.

O. Reg 170 Schedule 22 requires the municipality to identify any requirements of the Act, Regulations, Drinking Water Works Permit, Municipal Drinking Water Licence and any Order that the system failed to meet during the reporting period. There were no issues identified in 2023.